

Message

From: MacNicholl, Peter@DTSC [Peter.MacNicholl@dtsc.ca.gov]
Sent: 2/10/2020 4:57:43 PM
To: Fennessy, Christopher [christopher.fennessy@Rocket.com]; MacDonald, Alex@Waterboards [Alex.MacDonald@waterboards.ca.gov]; Swanson, Charles [Swanson.Charles@epa.gov]; Lae, Tom/SAC [Tom.Lae@jacobs.com]
CC: Bush, Dan (Dan.Bush@arcadis.com) [Dan.Bush@arcadis.com]; Rob Wilhelm (RWilhelm@Hargis.com) [RWilhelm@Hargis.com]
Subject: RE: Area 40 update
Attachments: ATT00001.txt

Thank you for the update and pictures Chris.

From: Fennessy, Christopher <christopher.fennessy@Rocket.com>
Sent: Thursday, February 06, 2020 10:29 AM
To: MacNicholl, Peter@DTSC <Peter.MacNicholl@dtsc.ca.gov>; MacDonald, Alex@Waterboards <Alex.MacDonald@waterboards.ca.gov>; swanson.charles@epa.gov; Lae, Tom/SAC (Tom.Lae@jacobs.com) <Tom.Lae@jacobs.com>
Cc: Bush, Dan (Dan.Bush@arcadis.com) <Dan.Bush@arcadis.com>; Rob Wilhelm (RWilhelm@Hargis.com) <RWilhelm@Hargis.com>
Subject: Area 40 update

Hi Everyone – Although we have had some relatively dry weather the last couple of weeks and it appears we have some dry weather for a bit longer, Area 40 is still too wet to re-mobilize at this time (see photos below). As expected based upon where the pre-work drainage location, all of the water is ponding on the east side where the char layer was found. Our BMPs are working well, no water is migrating off-site down the drainage. Unfortunately, that means it is backing up on site and we just have to wait for it to infiltrate or evaporate. We will continue to monitor and let you know when we can get back out. Chris

Christopher M. Fennessy, P.E.
Aerojet Rocketdyne, Inc.
Senior Manager, Environmental Remediation
PO Box 13222
Sacramento, California 95813-6000
Cell: 916-798-6103
Ph: 916-355-3341
Fax: 916-355-6145
Email: Christopher.Fennessy@Rocket.com







